

---

## 6. Level 6 Repair

---

### 6-1. S/W installation

#### 6-1-1. Required items in order to install S/W

- Installation program: Downloader Program ([Odin3 v1.85.exe](#))
- Tablet PC
- Data Link Cable
- Mobile device specific S/W: Binary files

#### ※ Settings




Legion1911



## 2. Enter into Download Mode

- Press down on Volume Down button and power key at same time for 10 seconds




- Press down on Volume Up button to enter device into download mode



### 3. Connect the device to PC via Data Cable.

Make sure that the one of communication port [ID:COM] box is highlighted in yellow. The device is now connected with the PC and ready to download the binary file into the device.



### 4. Start downloading binary file into the device by clicking Start Button on the screen.

the green colored "PASS!" sign will appear on the upper-left box if the binary file has been successfully downloaded into the device.

